

02/07/2026

Summary of report:

Between April 2026 and June 2026, Willowbank Quarry has responded to:

- **Summary of any complaints received**
No environmental complaints
- **Summary of any uncontrolled discharges to freshwater**
No uncontrolled discharges to freshwater.
- **Summary of the results of water quality monitoring undertaken in accordance with the Receiving Environment Water Quality Monitoring Plan**

12/04/2026: Both rainfall trigger limits reached. Manual sampling undertaken.
Exceedance levels not reached.

18/04/2026: Both rainfall trigger limits reached at both the Quarry and Fill Site.
Quarry exceedance: 30.37 NTU.
Fill Site exceedance: 15.71 NTU

20/04/2026: 24hr rainfall trigger limits reached at both the Quarry site and Fill Site.
Quarry exceedance: 55.5 NTU
Fill Site: Compliant

21/04/2026: 24hr rainfall trigger limits reached at both the Quarry site and Fill Site.
Quarry exceedance: 57.9 NTU
Fill Site: Compliant

- **Summary of exceedances of water quality trigger limits set in the Receiving Environment Water Quality Monitoring Plan and actions taken of site to reduce the likelihood of a reoccurrence.**

Isolated storm hit Wellington region in particular Judgeford, Porirua. The storm (193mm) shut down SH58 as flooding and damage to the roading network had the region under a state of emergency. Judgeford was broadcast on the national news as the area was continually hit over a 4-day period. The quarry acted days before the event ensuring all SRPs were ready and floc devices topped up. Additional dirty water drains added, and monitoring occurred throughout the event when access was approved. These actions minimised the effects as evident in the low Turbidity results over the period (70 NTU max recorded).

- **Summary of any exceedances of water quality compliance limits**

Attached – Water Monitoring.xlsx